

# Fractions and Decimals

1/64	0.015625	33/64	0.515625
1/32	0.03125	17/32	0.53125
3/64	0.046875	35/64	0.546875
<b>1/16</b>	<b>0.0625</b>	<b>9/16</b>	<b>0.5625</b>
5/64	0.078125	37/64	0.578125
3/32	0.09375	19/32	0.59375
7/64	0.109375	39/64	0.609375
<b>1/8</b>	<b>0.125</b>	<b>5/8</b>	<b>0.625</b>
9/64	0.140625	41/64	0.640625
5/32	0.15625	21/32	0.65625
11/64	0.171875	43/64	0.671875
<b>3/16</b>	<b>0.1875</b>	<b>11/16</b>	<b>0.6875</b>
13/64	0.203125	45/64	0.703125
7/32	0.21875	23/32	0.71875
15/64	0.234375	47/64	0.734375
<b>1/4</b>	<b>0.25</b>	<b>3/4</b>	<b>0.75</b>
17/64	0.265625	49/64	0.765625
9/32	0.28125	25/32	0.78125
19/64	0.296875	51/64	0.796875
<b>5/16</b>	<b>0.3125</b>	<b>13/16</b>	<b>0.8125</b>
21/64	0.328125	53/64	0.828125
11/32	0.34375	27/32	0.84375
23/64	0.359375	55/64	0.859375
<b>3/8</b>	<b>0.375</b>	<b>7/8</b>	<b>0.875</b>
25/64	0.390625	57/64	0.890625
13/32	0.40625	29/32	0.90625
27/64	0.421875	59/64	0.921875
<b>7/16</b>	<b>0.4375</b>	<b>15/16</b>	<b>0.9375</b>
29/64	0.453125	61/64	0.953125
15/32	0.46875	31/32	0.96875
31/64	0.484375	63/64	0.984375
<b>1/2</b>	<b>0.5</b>	<b>one!</b>	<b>1.00</b>



# Fractions and Decimals

1/64	.015625	11/32	.34375	43/64	.671875
1/32	.03125	23/64	.359375	11/16	.6875
3/64	.046875	3/8	.375	45/64	.703125
1/16	.0625	25/64	.390625	23/32	.71875
5/64	.078125	13/32	.40625	47/64	.734375
3/32	.09375	27/64	.421875	3/4	.75
7/64	.109375	7/16	.4375	49/64	.765625
1/8	.125	29/64	.453125	25/32	.78125
9/64	.140625	15/32	.46875	35/64	.796875
5/32	.15625	31/64	.484375	13/16	.8125
11/64	.171875	1/2	.5	53/64	.828125
3/16	.1875	33/64	.515625	27/32	.84375
13/64	.203125	17/32	.53125	55/64	.859375
7/32	.21875	35/64	.546875	7/8	.875
15/64	.234375	9/16	.5625	57/64	.890625
1/4	.25	37/64	.578125	29/32	.90625
17/64	.265625	19/32	.59375	59/64	.921875
9/32	.28125	39/64	.609375	15/16	.9375
19/64	.296875	5/8	.625	61/64	.953125
5/16	.3125	41/64	.640625	31/32	.96875
21/64	.328125	21/32	.65625	63/64	.984375

## Measuring Tips

